

**Element wise Outage Details of Alipurduar Transmission Limited for FY 2022 - 23**

Element Name	Outage		Restoration		Duration of Outage Attributable to						% Availability
	Date	Time	Date	Time	Inter-State Transmission LICENCE	OTHERS	System constraint/ Natural calamity/ Militancy	DEEMED AVAILABLE	Reason of Outage		
400 KV Alipurduar - Binaguri D/C Ckt-3	6-May-22	12:33:00	6-May-22	16:23:00	0:00:00	0:00:00	0:00:00	3:50:00	Line Tripped due to B-N Fault Distance 47.7 km from Alipurduar SS. Line tripped due to Tree branch infridged in the induction zone. There was severe ROW in between Tower no. 209 & 210. We have approched Police, Local & District administration to resolve ROW since last six months. Letter attached herewith. However villagers were adamant to provide access to cut the trees. Due to heavy loading in summer sag increased and tree branch came in induction zone and line tripped.	100	
400 KV Darbhanga - Saharsa D/C Ckt-2	9-May-22	0:24:00	9-May-22	3:17:00	0:00:00	2:53:00	0:00:00	0:00:00	Line Tripped due to Y-Ph Fault Distance 82.75 Kms from Darbhanga SS. Fault Location is in to PGCIL Scope after LILO.		
400 KV Darbhanga - Saharsa D/C Ckt-2	29-Sep-22	3:55:00	29-Sep-22	4:30:00	0:35:00	0:00:00	0:00:00	0:00:00	Line Tripped due to B-Phase Fault FC 5.11kA,Distance 40 km from Darbhanga.	100	

II

**Elements where restoration time has exceeded the standards specified in Regulation 5 (b)**

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
NIL	NIL	NIL
NIL	NIL	NIL
NIL	NIL	NIL

III

**Details of compensation paid by the inter-State transmission licensee**

Element Name	Violation of Regulation 5 (a)		Violation of Regulation 5 (b)		Compensation paid (in Rs.)
	% Availability rescribed	Actual % Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
NIL	NIL	NIL	NIL	NIL	NIL
NIL	NIL	NIL	NIL	NIL	NIL
NIL	NIL	NIL	NIL	NIL	NIL