

Element wise Outage Details of Sipat Transmission Limited for FY 2022 - 23

Element wise Outage Details of Bipat Transmission Limited for FY 2022 - 23										
Element Name	Outage		Restoration		Duration of Outage Attributable to					
	Date	Time	Date	Time	Inter-State Transmission Licensee	Others	System constraint/ Natural calamity/ Militancy	Deemed Available	Reason of Outage	% Availability
					Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min		
765KV BILASPUR (PS) - RAJNANDGAON CKT-1	21-May-2022	23:10:06	31-May-2022	23:59:59	00:00:00	00:00:00	240:49:53	240:49:53	765kv Bilaspur-Rajnandgaon Ckt-1&2 Tripped on Zone-1, R-ph to E/F. After line patrolling, it was observed that Tower Number-413 of 765kv Rajnandgaon-Bilaspur D/C was collapsed causing tripping of both 765kv Rajnandgaon Bilaspur Line-1 & 2. Rectification work is in progress.	100
765KV BILASPUR (PS) - RAJNANDGAON CKT-2	21-May-2022	23:10:06	31-May-2022	23:59:59	00:00:00	00:00:00	240:49:53	240:49:53	765kv Bilaspur-Rajnandgaon Ckt-1&2 Tripped on Zone-1, R-ph to E/F. After line patrolling, it was observed that Tower Number-413 of 765kv Rajnandgaon-Bilaspur D/C was collapsed causing tripping of both 765kv Rajnandgaon Bilaspur Line-1 & 2. Rectification work is in progress.	
765KV BILASPUR (PS) - RAJNANDGAON CKT-1	1-Jun-2022	0:00:00	7-Jun-2022	23:03:10	167:03:10	00:00:00	167:03:10	00:00:00	heavy cyclone in the region, thereby creating a "Force Majeure" occurrence. Line tripped on 21st May. Outage hours considered from 1st June for June month availability calculation.	96.1
765KV BILASPUR (PS) - RAJNANDGAON CKT-2	1-Jun-2022	0:00:00	7-Jun-2022	17:29:49	161:29:49	00:00:00	161:29:49	00:00:00	765KV Bilaspur-Rajnandgaon Ckt-1&2 Tripped on Zone-1, R-ph to E/F. Line had tripped due to collapse of Tower no 407. Tower collapsed due to heavy cyclone in the region, thereby creating a "Force Majeure" occurrence. Line tripped on 21st May. Outage hours considered from 1st June for June month availability calculation.	
765KV BILASPUR (PS) - RAJNANDGAON CKT-1	6-Aug-2022	19:16:49	7-Aug-2022	01:57:16	00:00:00	00:00:00	6:40:27	00:00:00	765KV Rajnandgaon-Bilaspur Ckt-1 Tripped on Zone-1 (L2-L3) fault Fault Location: 50.2kms Charging Code: WR-720 & NL-345 Line tripped due to cloth, which was used by farmers to cover samplings. Photographs and panchayat letter attached. Readiness for charging mail sent to WRLDC at 22:36Hrs. but due to line isolator issue at Bilaspur PGCIL SS, line charged at 01:57 Hrs. Mail attached.	99.77
765KV BILASPUR (PS) - RAJNANDGAON CKT-1	18-Mar-2023	9:26:43	18-Mar-2023	9:26:43	0:00:00	0:00:00	0:00:00	0:00:00	AR Successfully operated on R-Phase. Fault Type: L1-N Fault Location: 126.6kms Fault Current: Ir- 5.2 kA	99.35

II

Elements where restoration time has exceeded the standards specified in Regulation 5 (b)

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
NIL	NIL	NIL
NIL	NIL	NIL
NIL	NIL	NIL

III

Details of compensation paid by the inter-State transmission licensee

Element Name	Violation of Regulation 5 (a)		Violation of Regulation 5 (b)		Compensation paid (in Rs.)
	% Availability rescribed	Actual % Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
NIL	NIL	NIL	NIL	NIL	NIL
NIL	NIL	NIL	NIL	NIL	NIL
NIL	NIL	NIL	NIL	NIL	NIL